


## Signal Tracing from HDI to Interconnect to ROC









## Pin 1 on Hirose Connectors

Assume we want interconnect cables to be able to be plugged in to the HDI from either end.

**ROC Board Faces Downstream** Gray indicates connector on back-side of interconnect. Black is on front side Hirose Pin 1 (wedge #)

All Hirose connectors on ROC are oriented in the same way.